

Engine ECM Internal Error

Fault Code	Possible cause	Action
P0606	Engine ECM internal error	Contact Triumph service.
P1607 P1608	Engine ECM ride by wire internal error	