

Throttle Valve Drive Error

Fault Code	Possible cause	Action
P2111	Throttle valve drive error (stuck open)	View and note 'freeze-frame' data if available. View and note 'sensor' data. Check throttle body for mechanical malfunctions. Clear fault code and contact Triumph service if fault is still present.
P2119	Throttle valve drive error	
P2102	Throttle actuator control internal motor relay does not operate	
P2103	Throttle actuator control internal motor relay operates continually	